## 2015 MRC (effective February 8<sup>th</sup>)

As always, there are numerous changes to the residential code. Please review the following list for some of the significant changes:

- 1. Footing size per Table R403.1 In many cases, the old standard 16" x 8" footing will not be sufficient.
- 2. Mechanical ventilation is required for new homes. Houses are required to be more "air tight" so fresh air is important.
- 3. New homes and additions will be required to provide a blower door test not to exceed 4 ACH (air changes per hour).
- 4. A minimum 75% of lamps must be high efficacy.
- 5. GFCI devices are required for laundry and dishwasher circuits. Also, they must be readily accessible.
- 6. Garages are required to have a dedicated circuit.